








1












M 8x45 = 25 Nm Ø 8x19

2



1x M 7x30 Ø 7 Ø 7







B/E



6x M 8x20=25 Nm Ø 8x19





Handhabungshinweise

- EN - Handling
- FR - Indication relative à la manipulation
- NL - Bedieningsinstructie
- ES - Instrucciones de manejo
- IT - Avvertenze per il maneggio
- PL - Wskazówki obsługi
- PT - Nota sobre o manuseamento
- DA - Håndtering
- CS - āPokyny k manipulaci

